ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0572, W0677, W0574, W0576, W0586, W0582, W0596, W

Street Name
NA, 2nd Crs, 1st Main Rd

Significant Landmark
Devappa layout Mariyamma block

Segment No.
11/C-W0572/S082316

Total Length (m)
385.44

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	27.26	77.549770	13.063154	77.549737	13.063330	W0592	DEAD END
2	45.75	77.549595	13.062745	77.549999	13.062626	W0677	DEAD END
3	60.13	77.549530	13.062980	77.550056	13.062809	W0677	DEAD END
4	62.87	77.550154	13.062867	77.550694	13.062663	W0677	DEAD END
5	51.48	77.549820	13.063441	77.550268	13.063288	W0677	DEAD END
6	48.19	77.549914	13.063576	77.550333	13.063430	W0677	DEAD END
7	27.21	77.550168	13.063971	77.550403	13.063884	W0677	DEAD END
8	19.60	77.550523	13.063979	77.550694	13.063922	W0677	DEAD END
9	42.95	77.550362	13.064171	77.550733	13.064036	DEAD END	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura

Sanctioned Estimated Amount (Rs.)
4900000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-16-000009

Work Order No.

Work Order Date

Period of Extention

EE/BTP/BBMP/E-PMT/WO/192/2015-16	03/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/02/2016	02/02/2017	Yes

Contractor Details

Name of Contractor	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)**
K.SHANKAR REDDY		0.00
Phone No.	**E-Mail ID**	
8553121546		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
3		SURESH
Date of Inspection	**Remarks**	
21/09/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0572, W0677, W0574, W0576,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	21/09/2016	21/10/2016	COMPLETED
SE	VASU K M	21/09/2016	21/10/2016	COMPLETED
EE	YARAPPA REDDY	21/09/2016	21/10/2016	COMPLETED
AEE	SHIVAKUMAR	21/09/2016	21/10/2016	COMPLETED
AE	SURESH	21/09/2016	21/10/2016	COMPLETED
AE	SURESH	21/09/2016	21/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0572, W0677, W0574, W0576,